



Notice to Mariners

14 of 2024

Banktown North light re-established.

To all Ships Masters, Pilots, Fishermen, Yachtsmen, Ships Agents and water users on the river Boyne estuary.

Drogheda Port hereby gives notice that Banktown North navigation beacon has been re-established but is currently unlit.

Vessels entering and leaving Drogheda Port are advised to continue exercising extreme caution, give a wide berth at Banktown North navigation beacon 53 43.65N, 006 16.79W, and maintain a safe maneuvering speed in the vicinity of the Banktown North light (ref: British Admiralty Chart BA1431).

An updated notice will be issued once the light is operational.

Capt. Laurence Kirwan
Harbourmaster & Pilotage Superintendent
26.07.2024