



Notice to Mariners

14 of 2026

Amended 07.02.2026

Fouled Anchorage - Lost Anchor and Chain

To all Ships Masters, Pilots, Dredger Skippers, Fishermen & Ships Agents

Mariners are advised that the anchorage at the following positions is fouled by lost anchors and approximately four (4) shackles of chain:

Position A (30.01.2026)

Latitude: 53° 44.27' N

Longitude: 006° 11.52' W

Position B (07.02.2026)

Latitude: 53° 43.86' N

Longitude; 006° 10.12' W

Advisory:

Vessels are strongly advised to navigate with caution when manoeuvring or anchoring close to the above positions.

Anchorage within a safe distance of the above position is required, taking into account swinging radius and prevailing weather conditions, until further notice.

Action Required:

All mariners in the vicinity should remain vigilant and comply with HM office instructions.

This notice remains in effect until further updates are provided.

Capt. Laurence Kirwan
Harbourmaster & Pilotage Superintendent
30.01.2026

Amended 07.02.2026